

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:

Company Gregg Galecki Environmental Coordinator OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number: Inspection Type: Inspection Date

C0070005 COMPLETE

Start Date/Time

Thursday, January 18, 2007 1/18/2007 8:30:00 AM

End Date/Time:

1/18/2007 3:00:00 PM Last Inspection: Wednesday, December 06, 2006

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 4 Deg. F. InspectionID Report Number: 1197

Types of Operations

Accepted by: pgrubaug

1/22/2007

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SKYLINE MINE

Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

10,374.00	Total Permitted Total Disturbed		
79.12			
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

~	Federal		Underground
	State		Surface
	County	,	Loadout
	Fee		Processing
12.1			-
	Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The following permit conditions have been met or are being met:

- 1) Water Monitoring data is being sumitted in an electronic format to the Division.
- 2) Canyon Fuel Co. must submit all existing studies and data for the update of the PHC as a result of the mine inflows.
- 3) Canyon Fuel Co. must submit cumulative monthly flow data for discharges into Electric Lake and Eccles Creek.
- 4) Canyon Fuel Co. must have a qualified person compile and analyze past macroinvertebrate studies on Eccles Creek into one report.
- 5) Canyon Fuel Co. must initiate an update to and further evaluation of the Hydrologic and Channel-Stability Evaluation of Eccles and Mud Creek.

Permit Renewal was April 30, 2002, and expires on April 30, 2007. The state permit for full extraction in North Lease was approved by the state on December 2, 2005 and mining plan approval by the Secretary of the Interior was approved on February 24, 2006.

Inspector's Signature:

raun double

Date

Friday, January 19, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (803) 538-7458 • www.ogm.ut.uh.gov Permit Number: C0070005 Inspection Type: COMPLETE

Inspection Date: Thursday, January 18, 2007

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1	Permits, Change, Transfer, Renewal, Sale	V		~	
2.	Signs and Markers				
3.	Topsoil	V		~	
4.a	Hydrologic Balance: Diversions	~	ľ		
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		Y	
4.c	Hydrologic Balance: Other Sediment Control Measures	~			ļ
4.d	Hydrologic Balance: Water Monitoring	~	1	~	
4.e	Hydrologic Balance: Effluent Limitations	V	. 1	~	
5.	Explosives	~	***	===	
6.	Disposal of Excess Spoil, Fills, Benches	Y	1		
7.	Coal Mine Waste. Refuse Piles, Impoundments	y		V	
8.	Noncoal Waste	Y			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	~	: 1		()
11.	Contemporaneous Reclamation	~			1
12.	Backfilling And Grading	[🗸			
13.	Revegetation	V			
14.	Subsidence Control	Y	L .		
15.	Cessation of Operations	~		["]	
16.8	a Roads: Construction, Maintenance, Surfacing	V			i i
16.1	o Roads: Drainage Controls	V	_		į
17.	Other Transportation Facilities	Y .			
18	Support Facilities, Utility Installations	Y			[]
19.	AVS Check	~	·		
20.	Air Quality Permit	Y	[V	
21.	Bonding and Insurance	V]	~	
22.	Other		[]		

Permit Number: C0070005
Inspection Type: COMPLETE

Inspection Date: Thursday, January 18, 2007

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/005 was issued effective 04/30/2002 and expires 04/30/2007.

- -Certificate of Insurance policy number HDO G2 1732576, issued 07/31/2006 and terminates 07/31/2007.
- -UPDES permit # UT0023540 effective 12/01/2004 and expires @ midnight 11/30/2009.
- -Air Quality permit DAQE-AN0092007-03, issued June 24, 2003.
- -SPCC Plan dated 07/07/05. The Plan is P.E. certified, stamped, signed and dated by a Utah P.E.

2. Signs and Markers

The Mine ID signs are at the point of public access to the permit area and contain the required information. All other signs and markers are in accordance with the coal rules.

3. Topsoil

The two topsoil piles located on top of the refuse pile did not have topsoil identification signs. The operator will install signs on both piles.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The fourth quarter 2006 and annual 2006 pond inspections were conducted on November 27, 2006 and P.E. stamped dated and signed on January 8, 2007. No problems were noted.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2006 water monitoring is in the EDI website and is uploaded. Fourth quarter 2006 information has been received and will be entered into the EDI website. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

The discharge monitoring reports for December 2006 were viewed during the inspection. No parameters were exceeded.

7. Coal Mine Waste, Refuse Piles, Impoundments

The refuse pile appeared stable. The berm around the top of the refuse pile needs to be augmented and re-established in a few areas. No smokers were observed.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-AN0092007-03 was issued on June 24, 2003. The permit remains effective.

Inspection Continuation Sheet

Permit Number: C0070005
Inspection Type: COMPLETE

Inspection Date: Thursday, January 18, 2007

Page 4 of 4

21. Bonding and Insurance

The current bond is \$5,137,000.00 as of September 19, 2006. The previous bond amount was \$5,076,000.00.

The insurance is through Ace American Insurance Company policy HDO G2 1732576. The required minimum coverage has been met. The insurance includes XCU and has the proper language in the cancellation clause.